



10/748 604

CofC

Attorney Docket: 97895.00117

IN THE UNITED STATES. PATENT AND TRADEMARK OFFICE

In re Patent of:

Steward A. Levesque, et al.

Examiner: Prasad, Chandrika

Patent No.: 6,971,909

Group Art Unit: 2839

Issue Date: December 6, 2005

Confirmation No. 8227

For: **ANGLED PATCH PANEL ASSEMBLY**

Mail Stop: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JAN 19 2006
of Correction

**REQUEST FOR CERTIFICATE OF CORRECTION
PURSUANT TO 35 U.S.C. § 254 AND 37 C.F.R. § 1.322**

Sir:

Pursuant to 35 U.S.C. § 254 and 37 C.F.R. § 1.322, applicants respectfully request that a Certificate of Correction be issued in connection with the above-referenced U.S. patent to correct mistakes incurred through the fault of the U.S. Patent Office and Trademark Office ("PTO"). The subject patent was granted by the PTO on December 6, 2005 as U.S. Patent No. 6,971,909. The mistakes identified in the attached Certificate of Correction are clearly disclosed in the records of the PTO.

Accordingly, applicants respectfully request correction to the subject patent as identified on the enclosed Certificate of Correction. Prompt entry of the enclosed Certificate of Correction is respectfully requested. **No fee is due in connection with this Request.**

Respectfully Submitted,

Basam E. Nabulsi
Reg. No. 31,645
McCarter & English LLP
Four Stamford Plaza, 9th Floor
Stamford, CT 06902
Phone: 203-965-0601
Fax: 203-323-6513

Date: January 10, 2006

ME1\5422700.1

JAN 19 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,971,909

Page 1 of 1

APPLICATION NO. : 10/748,604

ISSUE DATE : December 6, 2005

INVENTOR(S) : Stewart A. Levesque and Lars R. Larsen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5,

Line 15, should read as follows:

--although alternative securement methods may be employed, as will be--

Column 6,

Line 54, should read as follows:

--first and second patch panel elements 102, 104. With--

Column 7,

Line 49, should read as follows:

--138 are bent outwardly along elongated bar 134 and are--

Column 7,

Line 58, should read as follows:

--face of patch panel elements 102, 104, e.g., between aligned--

On the face of the patent, the list of U.S. PATENT DOCUMENTS should include:

--6,866,541 3/2005 Barker et al.--

On the face of the patent, the list of OTHER PUBLICATIONS should include:

--PCT International Search Report dated May 6, 2005--

MAILING ADDRESS OF SENDER (Please do not use customer number)

McCarter & English, LLP
Four Stamford Plaza
107 Elm Street
Stamford, CT 06902

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

JAN 19 2006